### Approved For Release 2003/09/29 : CIA-RDP63-00313A000600130028-2

# TOP SEGRET

#### COR-OHER

Gopy 6 cf 19

	· · · · · · · · · · · · · · · · · · ·			
•	STAFF MEETING MINUTES - 2 June 1959 Maeting			
	PRESENT; Col. Burke 25	Χ´		
25X1	Mr. Cumingham Col. Geary			
25X1				
	L. EGLIN AFB SURVEY. Reported that the survey team examined both the main base and base #3 at Eglin. The unit can be accommodated at the main base now with a move to #3 base later. The use of the main base would be on an integrated basis for 10 to 12 months prior to the move to base #3. Base #3 would give complete separate facilities; however a hange.	X		
25X1	would be necessary and the cost for this would approximate 25  Approximately would be required to renovate 25  Eglin main base area. A joint tenancy/usage agreement will be worked up in accordance with AFR 11-5. Any bartering should be done at the Headquarters USAF level.			
25X1	ACTION: to prepare coordinated recommendation for Col. Burks's approval.			
	2 PARTS FAILURES. Project Directive 66-4 makes it mendatory that failures be reported. The question was raised as to whether or not this was being done on accumulators and flow meters. All are going through LAC for inspection and repair.  Uit's on inverters have come in and the depot is acting on them.  3306A amplifier is being converted and sent to the field.  Advised that the present system is satisfactory.	X		
	J. TRACKERS: Dr. Scott of Perkin-Elmer has advised the following alternatives regarding trackers: (a) Return them to P-E for complete repair; or (b) send a P-E representative to the field to do the repair. It was agreed that both malfunctioning trackers are to be returned to P-E for overhaul.			
25X1	ACTION: to arrange for return of carners.			

4 1 mm 3.

## Approved For Release 2003/09/29 TGA-RDF63-90813A099600130028-2

4. J-75 MODIFICATIONS. It has been determined that no concrete information can be presented in relation to fuel curves on the J-75. Four modifications have been approved. The fifth is to be approved later for retention at Edwards. Col. Geary advised that at least one or two engines would be needed in addition to the present eight. It was pointed out that possibly the Edwards contract pilots should be trained at their present location; however, Col. Burks favored flight training at Detachment B. He also advocated full J-75 wring-out at Detachment B before committing to operations. It was suggested that the J-57/P-31 figures be used for comparison.

ACTION:	houre befor	to establish criteria for minimum re daployment of the J-75.	25X <sup>2</sup>

#### CORONA

J. The integration of someone in ARPA was not agreeable to Mr. Bissell. It was recommended that liaison be conducted with ARPA and Mr. Parangosky was named as the liaison officer.

25X1 An ARPA representative at CORONA meetings was still considered a good idea according to Col. Sheppard has objections to Dr. Golovin. Col. Burke and are to discuss this 25X1 aspect.

Z. Firings are scheduled for 3 and 19 June and 6 and 16 July. It was not finally decided whether destruction devices would be recommended.

P. 2 of 3.

## Approved For Retease 2003/09/29 : 6 A-8 2 2 3 0 313A0 999 00130028-2

\_ 2 \_

25X1	advised that the CORONA access	
05V4	was reviewed on a monthly basis. He also advised tha	
25X1	concerned a time lag problem and does not be a second and does not be a	
		visiting 25X and 25X
25V1	Washington on 3 June and will have discussions with	aaa 207
25X1		25X
25X1	ACTION: to reply to	25)
	Dop. Chief, Admir	nistrative Br.
	OPD	
25X1		
	WILLIAM BURKE	
	Colonel, USAF	
	_	
	Acting Chief, DPD-DD/P	
	Distribution:	
	l - DD/P	
	2 - A-DD/P-P	
	3 - A/Ch/DPD	
	4 - Ch/SRS/DPD	
	5 - Admin/DPD	
	6 - Cover/DPD	
	7 - Dev Br/DPD	
	8 - Secur/DPD	
	9 - Pars/DPD	
	10 - Contr/DPD	
	ll - Mat/DPD	
	12 - Commo/DPD	
	13 - Ops/DPD	
	14 - R&D Officers/DPD	
	15 - Fin/DPD	
	16 - Col. Geary	
	17 - AirSec/DPD	
	18 - Admin Chrono/DPD	

P 3 cf 3.